



Track and Field

Site Inspection

KHSAA Form TR123
Rev. 1/05

Meade County High School

Site Inspection Requested by Gordon Bocock

DATE: 5-17-05

Pole Vault

Landing Pad 19' 8" wide 20' 2" deep 16'5" back of box Runway 130'	NO Pole Vault Area
Planting Box	N/A
Standards/Crossbar 13'8" – 14'8" Bar 14' 10"	N/A
Surrounding Area	N/A
Weigh In of Athletes	N/A
Coaching Box	N/A
Pole Vault Venue (General Notes)	None Available



Track and Field

Site Inspection

KHSAA Form TR123
Rev. 1/05

Meade County High School

High Jump	
Landing Pit 16' by 8'	Yes 16' x 8' 3 sections of Spring Co Padding
Standards/Crossbar 12' apart Bar – 12'	Yes 12' pole and 12' between standards
Surrounding Area	Asphalt run-up area
High Jump Venue General Notes	High jump pit moved due to water standing on the track because the county water company decided to flush the hydrants above the area that afternoon.

Long Jump and Triple Jump	
Landing Pit 9' by 15'	Yes 9' x 20'
Take Off Marks 12' or 8' 32' or 28'	Take off marks 8' and 28'
Rakes/Shovel Brooms	Rake and shovel were at the venue
Sand Level	Good and level



Track and Field

Site Inspection

KHSAA Form TR123
Rev. 1/05

Meade County High School

Surrounding Area	Clear for participants
Long Jump/ Triple Jump Venue	Good condition

Shot Put	
Circle	The circle was painted with the inside plain and the colored area outside the ring
Sector and Markings 40* or 60 *	40 degree sector
Surrounding Area	Area for the athletes waiting to compete was taped off with only an opening for them to approach the ring open.
Weight Implements	Implements were inspected but not weighed in. No scales
Shot Put Venue	Good Condition



Track and Field

Site Inspection

Meade County High School

Discus Throw	
Circle	Metal ring used for circle
Sector and Markings 40* or 60 *	40 degree sector
Surrounding Area	Throwing cage in good condition Area taped off for competitors and spectators
Weight Implements	Implements were inspected but not weighed. No Scales
Discus Throw Venue	Good Condition

Running Track	
Lanes Number & Size General overall Conditions and concerns	5 lanes 40" wide New rubberized track Good condition
Stagger Colors:	White - 2 turn stagger Blue - 3 turn stagger Red - 4 turn stagger Green - 1 turn stagger



Track and Field

Site Inspection

Meade County High School

Relay Colors:	4 x 100 Yellow to Yellow 4 x 200 Red, Red and Yellow 4 x 400 Green, Blue, Blue, Blue 4 x 800 Blue
Break Lines	Dashed green line
Hurdle Colors Overall condition of the hurdles	Girls 100 hurdles yellow marks Boys 110 hurdles blue marks 300 meter hurdles red marks Hurdles were new Had hurdle cart to move hurdles
Starting Blocks Number and condition Block Cart	5 new starting blocks in good condition There was no block cart since only 5 blocks
Starting Line Safety	Area taped off for competitors and starter
Finish Line Safety	Area taped off for competitors and timers
Surrounding Areas (This could include bleachers, fencing, tree limbs, etc.	The bleachers were taped off to keep spectators off of the track during competition. There is a fence on the inside of the track but it doesn't interfere with the runners
PA / Press Box	Yes used PA in press box to announce and call competitors to their events



Track and Field

Site Inspection

KHSAA Form TR123
Rev. 1/05

Meade County High School

<p>Officials Overall view of this Track and Field Complex</p>	<p>Very good track facility</p>
<p>Regional Meet Site (In your opinion would you recommend this facility be considered as a Regional Meet Site.</p> <p>If No what would they need to do to bring this facility into compliance.</p>	<p>No There are only 5 lanes, which is not enough for the size region they are in. No pole vault pit.</p>

Respectively submitted,

Please complete the Site Inspection Form
and e-mail to coachbo@charter.net and jtackett@khsaa.org